

QUALITY CODE 20D
QUALITY REQUIREMENTS FOR
MANUFACTURERS/DISTRIBUTORS

Part A:

The Seller is responsible for performing or having performed all inspections, tests, and calibration necessary to substantiate that the supplies or services furnished under this contract conform to contract requirements. Documentation (records) demonstrating compliance with this clause must be created and retained in accordance with the record retention clause of this purchase contract. Records must be maintained on file by the seller and made available for review by buyer upon request. If the specification for the parts has a qualified products list/qualified manufacturer list (QPL/QML), then the manufacturer of the product must be listed on the QPL/QML.

Part B:

When Seller is a Distributor, Seller shall identify in the Seller's shipping documentation the manufacturer's name and location (city and state) of the product being delivered.